

Cover for Holder OG (Clip) 5x20, OG (Halter) 5x20, UH, UHB



Description

- Fits to type: OG (Clip) 5x20; OG (Halter) 5x20; UH; UHB

References

[General Product Information](#)

Weblinks


[Approvals, RoHS, CHINA-RoHS, e-Store, Distributor-Stock-Check, Accessories, Product Change Notification \(PCN\)](#)

Technical Data

Fuse-Link	5 x 20 mm
Admissible Ambient Air Temp.	-40°C to 85°C
Storage Conditions	0°C to 60°C, max. 70% r.h.

Abmessungen

26.2 mm



Variants

Description	Order Number
Transparent Cover 1.6 W	0853.9561
Transparent Cover 2.5 W	0853.9562

Packaging Unit

Plastic Bag (100 pcs.)

Fuseholder Blocks & Clips

Cover OG, UHB, UH

www.schurter.com/pg02b

Cover for Holder OG (Clip) 5x20, OG (Halter) 5x20, UH, UHB



Description

- Fits to type: OG (Clip) 5x20; OG (Halter) 5x20; UH; UHB

References

[General Product Information](#)

Weblinks


[Approvals](#), [RoHS](#), [CHINA-RoHS](#), [e-Store](#), [SCHURTER-Stock-Check](#), [Distributor-Stock-Check](#)

Technical Data

Fuse-Link	5 x 20 mm
Admissible Ambient Air Temp.	-40°C to 85°C
Storage Conditions	0°C to 60°C, max. 70% r.h.

Dimensions

Length  26.2 mm



Variants

[Distributor-Stock-Check](#) | [SCHURTER-Stock-Check](#) | [e-Store](#)

Description	Order Number
Transparent Cover 1.6 W	0853.9561
Transparent Cover 2.5 W	0853.9562

Packaging Unit

Plastic Bag (100 pcs.)